### Cow Branch I Stream Restoration

### **Before Construction**





## **Cow Branch II Stream Restoration**

### **Before Construction**







## Lower Cabin Run Stream Restoration

**Before Construction** 






# Northgate Stream Restoration

### **Before Construction**





## **Deerfield Estates Stream Restoration**

### **Before Construction**





## **Deerfield Estates Stream Restoration**

### **Before Construction**





## **Cow Branch III Stream Restoration**

### **Before Construction**







## **Cow Branch III Stream Restoration**

### **Before Construction**





## **Cow Branch III Stream Restoration**

#### **Before Construction After Construction**





### **Oakstreet Stream Restoration**

### **Before Construction**





## **Oakstreet Stream Restoration**

**Before Construction** 



**After Construction** 



# Hylbrook Park Stream Restoration





**After Construction** 



# Hylbrook Park Stream Restoration





**After Construction** 



# **East Longview Stream Restoration**

### **Before Construction**





# **East Longview Stream Restoration**





**After Construction** 



# Dewey's Creek Reach 4 Stream Restoration







# Dewey's Creek Reach 4 Stream Restoration

**Existing Condition** 





# Dewey's Creek Reach 1 Stream Restoration

**Existing Condition** 





# Dewey's Creek Reach 1 Stream Restoration

**Existing Condition** 





## Reach 5 Stream Restoration









## Reach 5 Stream Restoration

### **Existing Condition**





## Powells 725 Phase 1 Stream Restoration

**Existing Conditions** 





## Powells 725 Phase 1 Stream Restoration

**Existing Conditions** 



