



## Electrical Service Inspection

Issued by: *Eric M Mays, P.E.*

Building Official

Effective: October 10, 2003

The requirements for Residential Electrical Service Inspections for services up to 400 amps, will require the service inspection to be scheduled along with the combination close-in inspection.

Failure to schedule these inspections together will constitute a "Not Ready for Inspection" rejection. The field inspectors will not field generate the service inspection.

With pre-approval of the Chief Electrical Inspector, the service inspection may, under special circumstances, be done *before* the close-in. Services greater than 400 amps may be called as separate inspections.